AUDIO SYSTEM

4610-00/4610-01/8610-22/8610-26/8620-22/8910-07/8930-01/

AUDIO SYSTEM

OVERVIEW AND INSTALLATION

1. AUDIO SYSTEM OVERVIEW...... 3

CONFIGURATION AND FUNCTION

4610-00 AUDIO CONTROL SWITCH ON	
STEERING WHEEL	0 4 00
8610-26 RADIO ANTENNA	8
8910-07 USB/AUX MODULE	سرحت دروجيتار

اولین سامانه دیجیتال تعمیرکاران خودرو در ایرا

REMOVAL AND INSTALLATION

4610-01 AUDIO CONTROL SWITCH	10
8930-01 AUDIO ASSEMBLY	12
8610-22 FRONT DOOR SPEAKER AND	
REAR DOOR SPEAKER	13
8620-22 DOOR TWEETER SPEAKER	14
8910-07 USB/AUX MODULE	15
8610-26 MICRO-POLE ANTENNA	16





8930-01


11 - 3

AUDIO SYSTEM

8930-01

OVERVIEW AND INSTALLATION

1. AUDIO SYSTEM OVERVIEW



Modification basis
Application basis
Affected VIN




CONFIGURATION AND FUNCTIONS

4610-00 AUDIO CONTROL SWITCH ON STEERING WHEEL

1) Locations and Functions

Action Sports uses DSI 6-speed automatic transmission. DSI 6-speed transmission has two Tip Tronic switches on the TGS lever and the steering wheel.



Increase or reduce volume





In radio mode

- Press briefly: Manul searching for a station.
- Press and hold: Automatic searching for a station.

In CD mode

- Press briefly: Play next/previous track.
- Press and hold: Move forward/backward in current track.

In CD-ROM/USB mode

- Press briefly: Play next/previous file or station automatically.
- Press and hold: Move forwards / backwards

Bluetooth Switch

To receive a call in Bluethooth mode, press this switch.

To reject a call, press and hold this switch.

POWER

Turns on and off the audio system.

MUTE

Stops audio output from audio system. To resume the audio output, press the button again.

MODE

Changes the audio mode in order.

AUDIO SYSTEM ACTYON 2013.11


Modification basis	
Application basis	
Affected VIN	

2) Components

ACTYON

The audio switches on the steering wheel includes audio remote control switches.

These switches operate supplied with 5 V and there are three connectors. Functions for each pin of the main connectors are shown in the table below.




Functions of main connector by pin			
Pin No.	Name	Pin No.	Name
31	Audio signal	36	N.C / CRUISE SIG (GSL)
32	Illumination (-)	43	N.C
33	Illumination (+)	48	(TIP SHIFT) ECU GND
34	N.C / ECU GND (GSL)	49	(TIP SHIFT) ECU SIG
35	N.C / ECU 5V (GSL)		

Modification basis	
Application basis	
Affected VIN	

11-6 4610-00



3) Circuit Diagram





AUDIO SYSTEM ACTYON 2013.11

ACTYON

▶ Audio Switches on Steering Wheel







Modification basis	
Application basis	
Affected VIN	

11-8

8610-26

VCTAON

8610-26 RADIO ANTENNA

1) Overview

The micro-pole antanna is installed on the roof panel.

2) Location



AUDIO SYSTEM ACTYON 2013.11

Modification basis	
Application basis	
Affected VIN	

8910-07 USB/AUX MODULE

The audio system with a MP3/CD player is equipped with USB/AUX module to play the mp3 files (including ogg, wma format files) stored in the portable music player or USB device.

1) Overview





The USB/AUX module of the audio system is located in the front of the gear lever, and has only one AUX terminal which has the same functions as the terminals of the AV system. But it only has stereo function because there is no monitor to display the video signal in the audio system.

For details of playing an external device using the USB/AUX module in the audio system with a MP3/CD player, refer to the Audio System section.

11-10 4610-01

ACTYON

REMOVAL AND INSTALLATION

4610-01 AUDIO CONTROL SWITCH

Preceding work

Disconnect the negative battery cable.

1. Unscrew the mounting bolts on sides of the steering wheel and remove the airbag module assembly.



4610-01

11-11

ELECTRI C

FUSE AND

SZICS

MMOBILI ZER

LUSTE R


L L

WIPER & MASHER

SENSOF

AUDIO YSTEM

2. Remove two audio switch mounting screw from each sides from the steering wheel and disconnect the main connector. Then, remove the audio switch assembly from the steering wheel.




3. Install in the reverse order of removal.


شرکت دیجیتال خودرو سامانه (مسئولیت محدود)

ولین سامانه دیجیتال تعمیرکاران خودرو در ایران

8930-01 AUDIO ASSEMBLY

- Preceding work 1. Disconnect the negative battery cable.
 - 2. Remove the center fascia panel.
- 1. Remove two mounting screws and disconnect the connector to remove the A/C assembly.





2. Remove four mounting screws and disconnect the connector on the back of the audio assembly.





3. Remove the audio assembly.





AUDIO SYSTEM ACTYON 2013.11

Modification basis	
Application basis	
Affected VIN	

ELECTRI C

FUSE

STICS

IMMO ZEF

AMP

SWIT SWIT


SENSOR

8610-22 FRONT DOOR SPEAKER AND REAR DOOR SPEAKER

Preceding work

1. Disconnect the negative battery cable and remove the door trim (refer to "Body" section).

1. Disconnect the speaker connector.



2. Unscrew four mounting screws and disconnect the connector to remove the door speaker.



Front Door	40W/2 Ω
Rear Door	40W/2 Ω





Modification basis	
Application basis	
Affected VIN	

11-14 8620-22

ACTYON

8620-22 DOOR TWEETER SPEAKER

Preceding work

- 1. Disconnect the negative battery cable and remove the door trim (refer to "Body" section).
- 1. Unscrew two speaker mounting screws from the removed the door trim to remove the speaker.



AUDIO SYSTEM ACTYON 2013.11


Modification basis Application basis Affected VIN

SWITCH

8910-07 USB/AUX MODULE

Preceding work

Disconnect the negative battery cable.



1. Remove the lower panel assembly located under the center switch panel by pulling it out by hand to remove the USB/AUX module connector.





2. Remove the four mounting screws securing the USB/AUX module from the detached lower panel assembly and remove the USB/AUX module.





Modification basis	
Application basis	
Affected VIN	

11-16 8610-26


ACTYON

8610-26 MICRO-POLE ANTENNA

- Preceding work 1. Disconnect the negative battery cable.
- 1. Remove the D pillar (A) from the rear of the vehicle and the right storage box (B) of quarter pannel trim to remove the C pillar (C).
- 2. Remove three fasteners (D) from the back of the headlining (tailgate) to lower the headlining (at rear side).




3. Disconnect the radio antenna cable and module connector.





A CAUTION

- Pull the arrow position (A) down to disconnect the cable and connector. Otherwise, the cable or wiring could be damaged.



AUDIO SYSTEM ACTYON 2013.11

Modification basis	
Application basis	
Affected VIN	

ELECTRI C

FUSE

SZICS

MMOBILI ZER

LUSTE R

LAMF

SWIICH

WIPER & WASHER

RAIN SENSOR

n A N





4. Unscrew the nut (19 mm).



Check the antenna and rubber packing for their installation status and damage. Also, remove any foreign material on the surface of roof panel.



Memo					
	/				
		0			0
					0
		•• • ••		0	
سئوليت محدود	درو سامانه (می	ديجيتال خو	شركت	(
خودرو در ایران					